63-66 STD COLUMN COUPLER REBUILD KIT


1963-1966 STD Column Coupler Rebuild Kit Instructions

- **1**. Install rivets, retainer, ground strap & rubber Rag Joint and flange. (if you don't have press to set rivets, use the bolts and nuts)
- 2. Install studs, retainers, rag joint, ground strap and other flange with nuts & lw.

KIT INCLUDES:

- 2 STUDS
- 2 RIVETS
- 2 BOLTS
- 1 RUBBER RAG JOINT
- 4 RETAINERS
- 1 GROUND STRAP
- 4 NUTS

Zip Part # SC-778



www.zip-corvette.com 1-800-962-9632